

Zlin Aviation s.r.o.

2. Května 685
763 61 Napajedla

Service Bulletin	N° 2	Date 01/oct/2007
------------------	------	------------------

CAUTION

Check mechanic fuel pump (fig1)

- **Airplanes affected**
All Savage power by Rotax engine
- **Reason**
In one case we found show wear on the mechanic fuel pump caused by camloc's vibration.
- **Subject**
You have to make a visually condition check of the mechanic fuel pump.
If you find abnormal condition send a high resolution picture of this part to mail address: savage.ulm@tiscali.it
After, Zlin Aviation will answer you about the eventually work to do.

