

**Zlin Aviation S.R.O.**

2. Kvetna 685  
763 61 Napajedla  
Czech Republic

Service Bulletin	N°01	19 SEP 2007
------------------	------	-------------

**CAUTION**

- **Airplanes affected:**  
all Savage airplanes and models
- **Reason:** We found an hazard modification on a Savage of an American customer
- **Subject:** We found in the airplane of a customer a modification not authorized from the Zlin Aviation s.r.o.. The customer has installed two metallic clips in the rear zone of the airplane over the rudder cable pulley like shown in the picture. It is mandatory to remove these metallic clips (that can wear the rudder cable) and to bring back the airplane in the original conditions. After that, is mandatory to check the cable. We remember you that **modifications** of Savage airplanes **are not admitted** if not authorized from Zlin Aviation s.r.o. because all modifications can cause serious injury to people or things.

